

## Release Information

# Virtual Studio Manager – VSM

## vsmStudio Release 25.2.1\_1 (B2486 Hotfix)

Author: STB  
Last updated: 2025-06-11  
Release Date: 2025-06-11

**Hotfix 25.2.1** – A hotfix is to be used exclusively to address a specific situation and may contain untested aspects both related and not related to the specific situation.

This Release introduces new features, enhancements, and fixes for the vsmStudio software. Please consult the changelog for additional details.

### Including

- RNDVSM-50835: Tie-lines with a source side HOME device are not correctly migrated from pre B2484. NOTE: Only works when migrating from a pre B2484 build and only with e.g., .edge IP receivers. There might still be other devices which are not detected. Please let us know if you encounter other devices with this issue and we can add them.
- RNDVSM-50818: Linked ports must be unlinked before option to delete a port is enabled.
- RNDVSM-50819: Crash when label exchange protocol or similar protocols are used.
- RNDVSM-50825: Crash when undoing edit operations to a button.
- RNDVSM-50826: Virtual Sub Panel are not synchronized correctly.

### Software-Download

The latest VSM software release versions can be downloaded from the Lawo Download Center @ <https://lawo.com/lawo-downloads>.

As always, **before updating, backup your system and refer to the changelogs/ release notes** of each component to see if your system can be updated. Please also make sure to check and understand all changes, as well as any known issues that may be stated in the changelogs.

As upgrades may introduce a file format change [FFC], which implies incompatibilities of the configuration file of vsmStudio, please make sure to create a backup of your VSM directory before you upgrade.