L|S|B

PATCH RELEASE ANNOUNCEMENT

Version 14.2.2

AVAILABLE AUG 28TH 2015

CONTENT

Amongst various changes and fixes, Patch Release 14.2.2 offers the following **enhancements**:

- ➢ Control: LDK Connect Gateway. A dynamic CCU to OCP assignment is possible (#31112)
- ➢ Control: Telemetric RCCP, Robotic Camera Control Panel (#41723)
- ➢ Quartz Extension to control Lock, Unlock, Protect, Unprotect (#41899)
- ➢ Controls TC Electronics D22 parameters Delay, Preset, Bypass (#41990)
- ➢ Grass Valley Imagestore 750: Keyer Control and Preview (#41583)
- ➢ Advanced Lock function for target keys allows to lock the target for the length of a specific timer.
- ➢ Connect ProBel panels directly to Smarthub instead of CommServer (#41924)

IMPORTANT NOTES & OPEN ISSUES

1. We could localize one critical issue, which **could not be fixed** prior to release. It is related to „**POOLING**". **Do not update systems using pooling with release 14.2.!!!**
   Regular OB Van systems will not be affected. We are working on a patch for this which will be available soon. More details can be found in Release Notes.
   The Problem will be solved as soon as possible.
2. As Microsoft has officially ended the support for Windows® Server 2003 and Windows XP, the previous vsmStudio build B1978 is the last to support Windows® Server 2003 and Windows® XP. **From build 2006, vsmStudio will not run under Windows® Server 2003**.

VERSIONS INCLUDED

- ➢ vsmStudio: 14.2.3 (Build2072)
- ➢ vsmGadgetServer: 5.2.2.118
- ➢ vsmGear: B0017
- ➢ vsmPanel: v3.4.7
- ➢ vsmSnap: v3.0.6
- ➢ vSNMP: 2.0.0.9

SOFTWARE DOWNLOAD

In order to enable you to upgrade systems with the latest version, this release can be downloaded from our online repository. As always, before updating, refer to the **release notes** to make sure your system can be updated.

http://private.l-s-b.de/LSB_Release_2014-2-2.zip

Best Regards,

Axel Kern

Product Management